

553 76<sup>th</sup> Street · Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number: 61684 Date: 11-13-2013

For the Account Of: Bru Textiles

Satenrozen 2A 2550 Kontich Belgium

Contact: Tineke Verbruggen

Client's Identification: FR One Venere

Test Performed California Fire Marshal Title 19: Section 1237 Small Scale Test – Interior Materials

Qualifications (Proposed Revision - 8/9/93)

## **TEST RESULTS**

Specimen #	AFTERFLAME	CHAR LENGTH
	(SECONDS)	(INCHES)
Length		
1	0.0	4.25
2	1.0	4.75
3	3.0	4.00
4	0.0	4.50
5	6.0	3.88
<b>AVERAGE</b>	2.0	4.28
6	0.0	4.00
7	0.0	4.63
8	0.0	5.00
9	0.0	4.25
10	0.0	4.50
<b>AVERAGE</b>	0.0	4.48

16	sieu.	
$\boxtimes$	Initially	

☐ After Laundering☐ After Dry Cleaning

## **ACCEPTANCE CRITERIA**

1. Average Flame Time (after flame) after removal of the flame source may not exceed 4.0 seconds for length or width

2. Char length may not exceed **6.0 inches** for any individual specimen.

**CONCLUSION** Based on the above Results and Acceptance Criteria, the item tested:

Does Not Comply

CERTIFICATION: I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

C. Venthumen