Korea Fire Equipment Inspection Corporation

136, Jigok-Dong, Giheung-Gu, Yongin-Si, Gyeonggi-Do, 446-909, Korea / TEL:+82-31-289-2900 / FAX:+82-31-287-9067

NO.2007-08-6602-26

# Report of the Requested Test

**1. Client**

Name : Oliver Delhome

Manufacture : FR-One N. V

Address : Satenrozen 2A, B-2550 Kontich, Belgium

**2. Product(sample)** : Web 01-Russet

**3. Request Date and Number :** No. 0708818, July 11, 2007

**4. Test Results**

| Items | Standards | Test Results | | | Reference |
|---|---|---|---|---|---|
| | | 1 | 2 | 3 | |
| After flame time | Less than 3 sec | 0.0 | 0.0 | 0.0 | |
| After glow time | Less than 5 sec | 0.0 | 0.0 | 0.0 | |
| Char area | Less than 30 ㎠ | 3.9 | 3.5 | 5.8 | |
| Char length | Less than 20 ㎝ | 3.0 | 2.9 | 3.1 | |
| Flame applied number | 3 or more | 3 | 3 | 3 | |

※ Above the result is tested by KOFEIS1001

※ Use : Control the quality of product

Reference : 1. This is to certify that the tested sample has been requested by the above mentioned manufacturer.

2. This result can't be used an advertisement, a lawsuit etc.

Date : August 06, 2007

*President* : Dong-Ho Nam

**Korea Fire Equipment Inspection Corporation**